

Sweat Union (Brass) - Male Flare x ID Solder

C&D Item No.	Size	Universal No	Pressure Rating	Pack qty
CD-218-0404	1/4 x 1/4	US3-44	130bar	1
CD-218-0406	1/4 x 3/8	US3-64	130bar	4
CD-218-0604	3/8 x 3/4	US3-46	130bar	1
CD-218-0606	3/8 x 3/8	US3-66	130bar	1
CD-218-0608	3/8 x 1/2	US3-68	130bar	1
CD-218-0610	3/8 x 5/8	US3-610	130bar	1
CD-218-0806	1/2 x 3/8	US3-86	130bar	1
CD-218-0808	1/2 x 1/2	US3-88	130bar	1
CD-218-1008	5/8 x 1/2	US3-108	130bar	1
CD-218-1010	5/8 x 5/8	US3-1010	130bar	1
CD-218-1012	5/8 x 3/4	US3-1012	130bar	1
CD-218-1212	3/4 x 3/4	US3-1212	130bar	1



Sweat Union (Brass) - Male BSP x ID Solder

C&D Item No.	Size	Pressure Rating	Pack qty
CD-219-0404	1/4 x 1/4	130bar	1
CD-219-0604	3/8 x 1/4	130bar	1
CD-219-0606	3/8 x 3/8	130bar	1
CD-219-0608	3/8 x 1/2	130bar	1
CD-219-0808	1/2 x 1/2	130bar	1
CD-219-0810	1/2 x 5/8	130bar	1
CD-219-1212	3/4 x 3/4	130bar	1



Union (Brass) - Male NPT x Female NPT

C&D Item No.	Size	Pressure Rating	Pack qty
CD-220-0202	1/8 x 1/4	130bar	1
CD-220-0402	1/4 x 1/8	130bar	1
CD-220-0408	1/4 x 1/2	130bar	1
CD-220-0604	3/8 x 1/4	130bar	1
CD-220-0608	3/8 x 1/2	130bar	1
CD-220-0804	1/2 x 1/4	130bar	1
CD-220-0806	1/2 x 3/8	130bar	1
CD-220-1208	3/4 x 1/2	130bar	1

